

Signal Hill dynamic stability modeling notes and assumptions

Models

Dynamic stability studies were conducted using GE PSLF 1.42_06.

1. The dynamic models used for the wind farm were the wind turbine models for the GE 1.5 and 3.6 MW Wind Turbine Generators. These models consist of the “gewtg” generator/converter model, the “exwtge” excitation (converter) control model, and the “wndtge” wind turbine control model.
2. Default values for the “gewtg” model were used. The machines were assumed to have Low Voltage Ride-Through (LVRT) capability.
3. Default values for the “exwtge” model were used:
 - a. The wind farm was assumed to have a centralized “WindVAR” controller.
 - b. The voltage controller was assumed to be closed-loop.
 - c. The regulated bus was assumed to be 34.5 kV collector bus.
 - d. The machine was set to regulate VARS as opposed to power factor.
4. Default values for the “wndtge” model were used. A single-mass model was used.

Procedure

Stability results were evaluated based on the WECC Planning Standards criteria for transient stability. For a single-contingency event, transient voltage dip may not exceed 30% at any bus, 25% at load buses, and may not exceed 20% for more than 20 cycles at load buses. Frequency variations may not be below 59.6 Hz for more than 6 cycles at load buses.

The following faults were studied to determine the effect of the Project on transient stability:

1. 3-phase fault at the Lamar 230 kV bus, cleared after 4 cycles by tripping the Boone-Lamar 230 kV line, circuit 2.
2. 3-phase fault at the Boone 230 kV bus, cleared after 6 cycles by tripping the Boone-Lamar 230 kV line, circuit 2.
3. 3-phase fault at the Lamar 115 kV bus, cleared after 6 cycles by tripping the Lamar 230-115 kV transformer.
4. 3-phase fault at the Colorado Green 230 kV bus, cleared after 4 cycles by tripping the Lamar-Colorado Green 230 kV line.
5. 3-phase fault at the Signal Hill 230 kV bus, cleared after 6 cycles by tripping the Signal Hill-Lamar 230 kV line.
6. 3-phase fault at the Midway 230 kV bus, cleared after 6 cycles by tripping the Boone-Midway 230 kV line, circuit 2.
7. 3-phase fault at the Comanche Station 230 kV bus, cleared after 6 cycles by tripping the Comanche Unit 1 generator and station load.
8. Single-line-to-ground fault at the Boone 230 kV bus, with a delayed clearing time of 20 cycles by tripping the Boone-Lamar 230 kV line, circuit 2.

9. Single-line-to-ground fault at the Comanche Station 230 kV bus, with a delayed clearing time of 20 cycles by tripping the Comanche Unit 1 generator and station load.
10. Single-line-to-ground fault at the Midway 230 kV bus, with a delayed clearing time of 20 cycles by tripping the Boone-Midway 230 kV line, circuit 2.
11. Single-line-to-ground fault at the Lamar 230 kV bus, with a delayed clearing time of 20 cycles by tripping the Boone-Lamar 230 kV line, circuit 2.

Results

The system was monitored for transient stability violations for each of the fault scenarios. Table 2 summarizes the results of the study. The wind generation tripped offline on undervoltage conditions for the 3-phase faults located on the Lamar and Boone 230 kV buses (Fault 1 and Fault 2). The generation tripped because the voltage at the collector bus dipped to less than 0.3 per-unit voltage.

Voltage and frequency dip violations were observed at Lamar at distribution level voltages for several of the fault cases. These are due to the tripping of the nearby Colorado Green wind turbines, and in the Project cases, the tripping of the Project's wind turbines.



Table 1 - Transient Stability Results – Base Case

	Fault Location	Action	Result
6	3PH at Midway 230 kV bus; 6 cycles	Trip Boone-Midway 230 kV line, circuit 2	System Stable, Colorado Green Wind Tripped
7	3PH at Comanche Station 230 kV bus; 6 cycles	Trip Comanche Unit 1	System Stable, Colorado Green Wind Tripped
8	SLG at Boone 230 kV bus; 20 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind Tripped
11	SLG at Lamar 230 kV bus; 20 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable

Table 2 - Transient Stability Results – Base Case with Network Upgrades (Signal Hill Generation Off) <dpb updated table on 4.26.5>

	Fault Location	Action	Result
1	3PH at Lamar 230 kV bus, 4 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind Tripped
2	3PH at Boone 230 kV bus, 6 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind Tripped Frequency Violation: 40.7 Hz for 11 cycles at CO GRN 34.5 <dpb note: need all RAS schemes that trip the CO GRN 230 kV line. Tripping fixes this problem.>
3	3PH at Lamar 115 kV bus; 6 cycles	Trip Lamar 230-115 kV transformer	System Stable, Colorado Green Wind Tripped <ul style="list-style-type: none"> • Overvoltage spike fixed at CO GRN 34.5 • Frequency violations fixed at CHENEY 69, FT HOLLY 69, HILLTOP 69, SPRNGFLD 69, SPRNGFLD 4.2, VILLAS 69, WALSH 69, T BUTTES 69
4	3PH at Colorado Green 230 kV bus; 4 cycles	Trip Lamar-Colorado Green 230 kV line	System Stable, Colorado Green Wind Tripped
5	3PH at Signal Hill 230 kV bus; 6 cycles	Trip Signal Hill-Lamar 230 kV line	System Stable, Colorado Green Wind Tripped <ul style="list-style-type: none"> • All overvoltage spikes fixed: CHENEY 69, CTY LAM 69, EADS 69, FT HOLLY 69, FT. LYON 69, GRANADA 69, HILLTOP 69, PROWERS 69, SPRNGFLD 69, SPRNGFLD 4.2, T BUTTES 69, VILAS 69, WALSH 69, WILOW CK 69, CO GRN 34.5 • All frequency violations fixed: CTY LAM 14.4
6	3PH at Midway 230 kV bus; 6 cycles	Trip Boone-Midway 230 kV line, circuit 2	System Stable, Colorado Green Wind Tripped <ul style="list-style-type: none"> • All frequency violations fixed: CTY LAM 14.4, CTY LAM 25, CTY LAM 4.2, HOLLY 25, HOLLY 4
7	3PH at Comanche Station 230 kV bus; 6 cycles	Trip Comanche Unit 1	System Stable, Colorado Green Wind Tripped <ul style="list-style-type: none"> • All frequency violations fixed: CTY LAM 14.4, CTY LAM 25, CTY LAM 4.2, HOLLY 25, HOLLY 4, CTY LAM 69, FT. LYON 69, PROWERS 69
8	SLG at Boone 230 kV bus; 20 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable
9	SLG at Comanche Station 230 kV bus; 20 cycles	Trip Comanche Unit 1	System Stable
10	SLG at Midway 230 kV bus; 20 cycles	Trip Boone-Midway 230 kV line, circuit 2	System Stable
11	SLG at Lamar 230 kV bus; 20 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable

12	3PH at Boone 230 kV bus; 6 cycles	Trip Boone 230-115 kV transformer	<p>System Stable, Colorado Green Wind Tripped</p> <p>Voltage and Frequency Violations:</p> <ul style="list-style-type: none"> • Voltage dip > 25% at load buses: BOONE 69, FOWLER 69, HUERFANO 69, LAJUNTAW 69, LS ANMAS 69, 4.2, MANZANOL 69, ORDWAY 69, PHILLIPS 69, ROCKYFRD 69, SNEPESTA 69 • 43.0 Hz for 11 cycles at CHENEY 69, FT. HOLLY 69, HILLTOP 69, SPRNGFLD 69, 4.2, T BUTTES 69, VILAS 69, WALSH 69, WILOW CK 69 • 47.2 Hz for 11 cycles at CTY LAM 69,25, 14.4, 4.2, EADS 69, FT. LYON 69, GRANADA 69, HOLLY 25, 4.0, PROWERS 69, WILOW CK 69 <p>Post-transient voltage deviation of > 5%:</p> <ul style="list-style-type: none"> • 0.86 to 0.88 pu final voltage at FOWLER 69, LAJUNTAW 115, LS ANMAS 4.0, MANZANOL 69, ORDWAY 69 • 0.90 to 0.95 pu final voltage at APT MEM 115, APT PARK 115, BOONE 115, 69, CTY LAJ 69, 13.8, DOT 115, HUERFANO 69, LA SEPCA 69, LAJ IP 69, LAJUNTAW 69, LS ANMAS 69, NTHRIDGE 115, PHILLIPS 69, ROCKYFRD 69, SNEPESTA 69
----	-----------------------------------	-----------------------------------	---






Table 3 - Transient Stability Results – Case with 69 MW Signal Hill Wind and Network Upgrades <dpb updated table on 4.19.5>

	Fault Location	Action	Result
1	3PH at Lamar 230 kV bus, 4 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind Tripped
2	3PH at Boone 230 kV bus, 6 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind Tripped, Signal Hill Wind Tripped. New frequency violations: • 59.4 Hz for 6 cycles at CTY LAM 14.4
3	3PH at Lamar 115 kV bus; 6 cycles	Trip Lamar 230-115 kV transformer	System Stable, Colorado Green Wind Tripped New frequency violations: • 59.5 Hz for 7 cycles at CHEN TAP 69, CHENEY 69, FT HOLLY 69, HOLL TAP 69
4	3PH at Colorado Green 230 kV bus; 4 cycles	Trip Lamar-Colorado Green 230 kV line	System Stable, Colorado Green Wind Tripped
5	3PH at Signal Hill 230 kV bus; 6 cycles	Trip Signal Hill-Lamar 230 kV line	System Stable, Colorado Green Wind Tripped, Signal Hill Wind Tripped
6	3PH at Midway 230 kV bus; 6 cycles	Trip Boone-Midway 230 kV line, circuit 2	System Stable, Colorado Green Wind Tripped, Signal Hill Wind Tripped
7	3PH at Comanche Station 230 kV bus; 6 cycles	Trip Comanche Unit 1	System Stable, Colorado Green Wind Tripped, Signal Hill Wind Tripped New frequency violations: • 59.6 Hz for 7 cycles at PUEBLO 69 ⁱ
8	SLG at Boone 230 kV bus; 20 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable
9	SLG at Comanche		
	SLG at Midway 230 kV bus; 20 cycles	Trip Boone-Midway 230 kV line, circuit 2	System Stable
11	SLG at Lamar 230 kV bus; 20 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable
12	3PH at Boone 230 kV bus; 6 cycles	Trip Boone 230-115 kV transformer	System Stable, Colorado Green Wind Tripped; Signal Hill Wind Tripped

Table 4 - Transient Stability Results – Base Case with GI-2004-2 (Colorado Green Expansion)

	Fault Location	Action	Result
1	3PH at Lamar 230 kV bus, 4 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind 1 & 2 Tripped
2	3PH at Boone 230 kV bus, 6 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind 1 & 2 Tripped
3	3PH at Lamar 115 kV bus; 6 cycles	Trip Lamar 230-115 kV transformer	System Stable, Colorado Green Wind 1 & 2 Tripped
4	3PH at Colorado Green 230 kV bus; 4 cycles	Trip Lamar-Colorado Green 230 kV line	System Stable, Colorado Green Wind 1 & 2 Tripped
5	3PH at Signal Hill 230 kV bus; 6 cycles	Trip Signal Hill-Lamar 230 kV line	System Stable, Colorado Green Wind 1 & 2 Tripped
6	3PH at Midway 230 kV bus; 6 cycles	Trip Boone-Midway 230 kV line, circuit 2	System Stable, Colorado Green Wind 1 & 2 Tripped
7	3PH at Comanche Station 230 kV bus; 6 cycles	Trip Comanche Unit 1	System Stable, Colorado Green Wind 1 & 2 Tripped
8	SLG at Boone 230 kV bus; 20 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind 1 & 2 Tripped
9	SLG at Comanche Station 230 kV bus; 20 cycles	Trip Comanche Unit 1	System Stable
10	SLG at Midway 230 kV bus; 20 cycles	Trip Boone-Midway 230 kV line, circuit 2	System Stable
11	SLG at Lamar 230 kV bus; 20 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind 1 & 2 Tripped

Table 5 - Transient Stability Results – Case with GI-2004-2 and 69 MW Signal Hill Wind

	Fault Location	Action	Result
1	3PH at Lamar 230 kV bus, 4 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind 1 & 2 Tripped, Signal Hill Wind Tripped
2	3PH at Boone 230 kV bus, 6 cycles	Trip Boone-Lamar 230 kV line, circuit 2	
3	3PH at Lamar 115 kV bus; 6 cycles	Trip Lamar 230-115 kV transformer	
4	3PH at Colorado Green 230 kV bus; 4 cycles	Trip Lamar-Colorado Green 230 kV line	
5	3PH at Signal Hill 230 kV bus; 6 cycles	Trip Signal Hill-Lamar 230 kV line	
6	3PH at Midway 230 kV bus; 6 cycles	Trip Boone-Midway 230 kV line, circuit 2	System Stable, Colorado Green Wind 1 & 2 Tripped, Signal Hill Wind Tripped • 59.5 Hz for 6 cycles at CTY LAM 14.4
7	3PH at Comanche Station 230 kV bus; 6 cycles	Trip Comanche Unit 1	System Stable, Colorado Green Wind 1 & 2 Tripped • 59.5 Hz for 7 cycles at CTY LAM 14.4
8	SLG at Boone 230 kV bus; 20 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind 1 & 2 Tripped, Signal Hill Wind Tripped • 59.5 Hz for 7 cycles at CTY LAM 14.4
9	SLG at Comanche Station 230 kV bus; 20 cycles	Trip Comanche Unit 1	System Stable
10	SLG at Midway 230 kV bus; 20 cycles	Trip Boone-Midway 230 kV line, circuit 2	
11	SLG at Lamar 230 kV bus; 20 cycles	Trip Boone-Lamar 230 kV line, circuit 2	System Stable, Colorado Green Wind 1 & 2 Tripped, Signal Hill Wind Tripped

ⁱ Frequency dip is likely due to under-damped model for generator 70334 “PUB DSLS”. May also be due to interactions between 70334 generator and 70338 load “HP.” See plots attached to this footnote.

