
Xcel Energy South Control Center Daily Operations Report

Date: 8/13/2008

Out Time: *In Time:*
(Begin:) *(End:)*

3:00		Eddy Co HVDC is offline, no schedules.
6:51	14:31	Kirby Sw Sta to WTU Shamrock T54. AEP/ Corpus called about taking their 138/69 kv transformer out from 0700 to 1700
		AEP has work complete and back to normal
8:05		N/S TLR 3A released to 0 Import tie TLR 3A released to 0
8:07	16:38	Sundown Interchange to Terry Co Interchange V55 - change out arms.
8:13	21:06	Lea National to Maddox Sta V83 - Change out arms & pull maint.
		Temp. release & Temp Terminated
8:21	15:11	Tuco Interchange - stacking transformer
8:51	13:53	Bailey Co Interchange repairing West transformer alarm
8:52	16:41	Plainview - checking RTU & new cap bank
9:09	17:12	TLR 3B on imports SPP released TLR to zero
9:46	15:00	Hale Co Interchange - Testing relays one-at-a-time
		Released
10:20	12:27	Texas Co Interchange 115KV breaker 0804 is by-passed for condition assessment.
10:38	14:38	Moore Co Interchange 115KV BKR M952 - make relay setting changes and change CT ratio.
11:00	17:00	Time correction "J" in effect. Time was fast. End TEC "J" and regulate to 60hz
15:44	18:11	Riverview Interchange 115KV BKR R900 - make relay setting changes, change CT ratio, and calibrate metering.

Xcel Energy South Control Center Daily Operations Report

Date: 8/13/2008

Out Time: In Time:
(Begin:) (End:)

- 16:09 19:54 Hansford Sw Sw to Texas Co Interchange T88 - H/L TWR for contractor to install common structure.

Temp. Release & Temp. Terminated
- 17:03 17:03 Bailey Co Interchange to Lamb Co Interchange Y80 operated and closed back.
Bailey Co 69KV BKR 3867 had 1 operation.
There is no fault location indication at this station.
Thunderstorms in the area.
10.5 MW on BKR when it operated.
- 17:35 17:58 Carriers tested OK, except for the PCA carriers. The RTU is down.
- 18:51 19:50 Eddy Co Static Var Fan fail alarm

Fan has shorted winding. Alarm cleared
- 21:47 21:47 Roosevelt Co Interchange to Tolk Sta #1 K18. 230KV Ocb TK21 @ Tolk & 230kv Gcb 4K60 @ Roosevelt opened,closed, 1 operation

Storms in area
- 22:48 Bailey Co Interchange - low oil alarm on the East 115/69 Kv Tf. Notified DDC to dispatch a man. Everything looked good, will check into more detail. It may be a gauge or instillation problem.
- 23:51 SPP issued a 3A TLR on the N/S flow.