

---

---

## *Xcel Energy South Control Center Daily Operations Report*

---

---

*Date: 1/4/2010*

---

---

*Out Time: In Time:*  
*(Begin:) (End:)*

**9:14**                      **Wolfforth Interchange to Yuma Interchange T72 - Wolfforth Bkr 7940 out to replace relay package.**

**9:50**      **12:00**      **Roswell Comm line RCC6 down except for Taylor and Eunice. Notified Comm tech. Probably noise on phone line. Tech going to area. Noise was on Drinkard comm line. Comm tech left Drinkard off. Reported to phone Co.**

**10:51**                      **Potter Co Interchange Ca on Brk 2K40**

**11:13**      **13:32**      **Cochran Co Interchange - Bkr 9920 Low gas alarm. Notified Lub Sub. 1332 Added SF6 gas- TWR terminated**

**11:19**      **11:27**      **Maddox - Blew fuse in RTU all breakers indication showed open. Problem corrected.**

**12:12**      **Maddox Sta to Taylor Sw Sta T14 - Maddox new Bkrs U925 and U935 installation terminated and still needs to be checked out. Line from Sanger to Maddox closed back in. MOD 4J13 operated by SCADA ok.**

**13:23**      **15:32**      **TLR 3B implimented on exports SWPP released TLR 3B.**

**16:30**      **16:43**      **Carriers tested OK**

**17:18**      **19:27**      **SPP issued a TLR 3B on exports. SPP released TLR 3B on exports.**