
Xcel Energy South Control Center Daily Operations Report

Date: 3/1/2010

Out Time: In Time:
(Begin:) (End:)

- 6:28 SPP released TLR to level zero on flowgate 5368 - (Loss of Swisher/Tuco K1 will overload Kress/Hale V72)
- 8:37 Harrington Sta to Potter Co Interchange K58 was verified to still be switched out and permission was given to go back to work.
- 8:39 Maddox - TWR 840230 has been released
- 8:39 Maddox - TWR 840284 has been established to replace breaker U900.
- 10:19 14:40 Martin Sw Sta 115KV BKR out for C.A.
- 11:51 11:53 Floyd Co Interchange to Tuco Interchange Z36
- Floyd Co Breaker 8867 opened when Circuit T65 locked out. 8867 did not reclose automatically. Operator closed 8867 by SCADA and it held. Z36 is on the same towers as T65 in this area. Customers affected are Allmon and LEC's Petersburg and Harmony.
- 11:51 Crosby Co Interchange (9955) to Floyd Co Interchange (6J30) T65 operated three times and locked out. Fault location showed to be 2 miles outside of Floyd Co. No customers are affected by this. Patrolman is headed that way.
- Patrolman reported a vehicle accident caused this outage.
- 13:19 14:57 Denver City Interchange - TWR to perform a CA on breaker W980.
- 15:04 Crosby Co Interchange to Floyd Co Interchange T65 is out of service and Z36 is isolated from switch 3702 to 3705 to repair a broken structure due to a vehicle accident.
- 16:31 Carriers tested good.