

---

---

## *Xcel Energy South Control Center Daily Operations Report*

---

---

*Date: 3/6/2010*

---

---

*Out Time: In Time:*  
*(Begin:) (End:)*

|       |       |   |
|-------|-------|---|
| 1:10  | 9:05  | SPP issued TLR 3B on Temp. #1 flowgate. Loss of K11 Bushland to Deaf Smith overloads V5 Osage to Canyon.<br><br>0905 Temp #1 released. Rs   |
|       | 1:44  | SPP released TLR to zero for flowgate # 5354. Loss of Amarillo South to Swisher K63 overloads Randall to Happy T66.   |
| 12:26 | 13:38 | Bailey Co Interchange - Battery grd alarm. Called out sube to check.<br>Ground is small per sube. 4.0 volt diff. Will check again Monday.   |
|       | 13:22 | Osage Sw Sta to South Georgia Interchange V70 - work to replace cross arms completed  |
| 14:10 | 14:37 | Carriers tested OK  |
| 15:22 |       | SPP issued TLR 3B for flow gate Temp #1 - Loss of K1 (Bushland to Deaf Smith) overloads V72(Osage to Canyon)  |
| 16:45 | 17:27 | Eddy Co Interchange to Pecos Sw Sta T61 - Central valley reported line feeds out of Eddy Co. 2 miles East on Hwy 82 has pole on fire. Notified DCC to send serviceman to check. Serviceman reported ckt is T61. Notified Transmission Contr. Manager.<br>Line operated and was reopened by Scada control.   |
| 17:27 | 17:27 | Eddy Co Interchange to Pecos Sw Sta T61 - Operated<br>17:27 Eddy Bkr 4990 and Pecos Bkr 3H245 O/C<br>17:29 Opened both ends by Scada control after field report that T61 had structure on fire. Pole on fire and cross arm burned up and fell causing phase to fall against pole.<br><br>Tagged discs open on TWR 840501 issued to TCC operator.<br>Will establish a dead-line TWR for System Line crew that will make the repairs. |