
Xcel Energy South Control Center Daily Operations Report

Date: 9/3/2008

Out Time: In Time:
(Begin:) (End:)

1:06 Eddy Co HVDC off line no schedules.

2:20 Hereford Interchange North 115/69 KV transformer nitrogen pressure low.

2:29 SWPP released TLR's on N/S and imports to zero

4:00 TEC "A" ended and regulating to 60hz

7:05 SPP Market System back to normal. Back to ICCP+EI control scheme.

7:12 SPP issued TLR 3B on N/S Flow.

7:40 Sundown Interchange to Terry Co Interchange V55 - H/L change arms on double ckt.

8:57 Eddy Co HVDC - on line for schedules.

9:51 SPP issued TLR 3A on SPP/SPS Import Tie.

13:01 14:54 Lamb Co Interchange - test relays one-at-a-time

13:13 13:35 Denver City Interchange - W980 relay setting changes

14:14 16:39 Etter Rural 115KV BKR 5980 - test UF relay

22:00 TEC "B" ended. Returned to 60Hz.

22:44 23:52 Eddy Co Static Var System cooling level alarm

Switchman added Glycol to system. Alarm back to normal.