

---

---

## *Xcel Energy South Control Center Daily Operations Report*

---

---

*Date:* 12/25/2009

---

---

*Out Time:* *In Time:*  
*(Begin:)* *(End:)*

2:55	3:34	Potash Junction Interchange substation intrusion alarm. Notified SOC SOC reports the substation is secure.
5:02	7:39	Lamb Co Interchange - Low operating pressure alarm. Dispatched sube to check.  Sube found the compressor belt was slipping on bkr 3850. He took the belt off, warmed it up and replaced it. The compressor was able to pump then.
5:10		SPP issued a TLR 3B on temporary flow gate # 19 - Loss of K16 (Harrington-Nichols) overloads K17 (Harrington-Nichols).
6:30	9:14	SPP issued a TLR 3B on Temp 5 - the loss of K46, Plant X to Sundown, will overload K42, Talk to Tuco.
10:42	11:15	Tuco Interchange - Scada showed a Gas Detection Alarm on the south 230/115kv transformer. Requested a sube to check.  The alarm has gone in and out a couple of times and at 1115, shows normal.
11:00	23:00	Time error correction "H" started. End of TEC.
15:44	17:30	SPP issued TLR 3A on N/S Flow. SPP released TLR to 0.