
Xcel Energy South Control Center Daily Operations Report

Date: 2/23/2010

Out Time: In Time:
(Begin:) (End:)

3:02	4:30	Hale Co Interchange - low oil level alarm on the north 115/69kv transformer. Sube said cold weather causing alarm, oil level ok.
7:06	7:07	Harrington Sta to Potter Co Interchange K58. Potter BKR 2K40 O/C and BKR 2L35 O/C Harrington BKR FK30 O/C. Fault recorder 8.8 miles from Harrington Fault recorder 1.1 miles from Potter
10:55	16:50	Osage Sw Sta BKR 5H85 TWR to ca breaker.
11:00	23:00	Start of TEC "H" Time was fast. End of TEC.
11:30	11:41	Oasis Interchange BKR 3H105 TWR to add SF6 gas.
16:37		Carriers tested good.