
Xcel Energy South Control Center Daily Operations Report

Date: 3/2/2010

Out Time: *In Time:*
(Begin:) *(End:)*

7:56	11:23	Bowers Interchange BKR 5710 Breaker CA.
9:14		Maddox - TWR 840287 has been established to replace disconnect U918.
9:53		Maddox - TWR 840286 has been established to replace disconnect U902.
10:14		Deaf Smith Co Interchange BKR 5H50 CA.
10:28	12:46	Martin Sw Sta BKR 2H65 - TWR for CA.
10:38	15:07	Denver City Interchange - Performing a CA on breaker W980.
11:31	14:00	Bowers Interchange BKR - TWR to 5720 Breaker CA.
11:37	16:38	Osage Sw Sta BKR 5H25 - TWR to CA Breaker.
	15:37	Crosby Co Interchange to Floyd Co Interchange T65 - TWR 840352 has been released and terminated.
16:34		Carriers tested good
18:41		SPP issued TLR level 3B on SPSSPPTIES export flowgate.
19:18	20:05	SPSSPPTIES, contacted RC with concern about flow since TLR was issued. RC indicated they were working on it.
		I instructed XEM to control ACE as close to 0 as possible.