
Xcel Energy South Control Center Daily Operations Report

Date: 3/11/2010

Out Time: *In Time:*
(Begin:) *(End:)*

4:45 Curtailment - Called for Import limits of 484 due to line outage between W. Childress and Hollis Tap on AEPTN system.

8:30 16:35 Curtailment - SPP issued TLR 3B on Flowgate 5370 (loss of either K16/K17 Harrington to Nichols - will overload the other ckt either K16/K17)

SPP released TLR to level 0.

8:48 10:26 Pecos Sw Sta BKR 3H245 CA on Breaker

9:07 12:22 Lamb Co Interchange to Tuco Interchange Y79 is under hot line conditions on the Tuco end to allow SPEC to perform line maintenance on their portion of the circuit.

9:48 Lamton Interchange to Springlake Z64 pole change on STR #88. Working between switches 8706 and 3730.

9:58 11:49 Yoakum Co Interchange - TWR for Op checking the South Transformer and dobling the highside breaker.

10:28 Cochran Co Interchange - Opened breaker 7835 to relieve loading on the West tranformer.

10:39 13:28 Maddox - Hot line conditions on circuits V90 and V83 to remove the shoo-fly tying those circuits together.

11:23 Graham Interchange TWR 840396 on breaker 6F65 has been released and terminated.

11:30 Graham Interchange - Performing a CA on breaker 6F60.

11:38 11:39 Lea National to Maddox Sta V83 Operated breakers U915 and U925 one time and closed back. Cause unknown.

12:52 12:52 Lea National to Maddox Sta V83 Operated breakers U915 and U925 one time and closed back. Cause unknown.

13:00 13:01 Lea National to Maddox Sta V83 Operated breakers U915 and U925 one time and closed back. Cause unknown.

Xcel Energy South Control Center Daily Operations Report

Date: 3/11/2010

Out Time: In Time:
(Begin:) (End:)

13:02 13:03 Lea National to Maddox Sta V83 Operated breakers U915 and U925 one time and closed back. Cause unknown. Opened U925 at 13:03 by control switch. Breaker operations stopped. Leaving U925 open until problem is investigated.

15:25 Maddox TWR 840285 to replace switch U901 has been completed, released, and terminated.

15:39 17:27 Maddox - The Shoo-fly between V90 and V83 has been re-installed to feed V83 from Cunningham.

16:41 East Plant CA-Maint BKR 2K50 and A910.

16:44 19:33 Curtailment - SPP issued TLR 3B on flowgate 5354 (loss of K63 Ama S./ Swisher - overloads T66 Randall/ Happy).
TLR to level 0.

17:24 Carriers tested good.