

---

---

# *Xcel Energy South Control Center Daily Operations Report*

---

---

*Date:* 8/15/2008

---

---

*Out Time:* *In Time:*  
*(Begin:)* *(End:)*

0:29 SPP issued a 3B TLR on the N/S.

2:41 6:20 Crosby Co Interchange to Tuco Interchange Y84 - isolate down line section in order to feed SPEC - Hettler, SPEC - Idalou, and Vickers.

TWR released @ 0451.

Vickers energized from Crosby @ 0453  
SPEC - Idalou energized from Crosby @ 0518  
SPEC - Hettler energized from Stanton @ 0620

2:59 Eddy Co HVDC - off line no schedules.

3:28 SPP released the TLR on the imports.

4:00 TEC "K" to end and return to 60 Hz.

6:35 N/S TLR 3A released to 0

6:52 8:00 Hansford Sw Sw to Texas Co Interchange T88 - H/L to install common str and other work on T88

7:54 21:24 Lea National to Maddox Sta V83 - H/L to change out arms and pull maint.

Temp. Release & Temp. Term

8:00 Seven Rivers Inspect the cap bank and packs.

9:10 10:11 Hale Co Interchange to Plainview/Tuco Intg Z18 - line section out between sw 9702 & 9791 due to phase down.

Line repaired and back in service.

9:30 10:33 Shell CO2 BKR 8955 OP CK

10:08 Stanton Y85 to Planters SW 7756 line was patrolled and nothing was found .  
At Stanton closed switch 6766 buy supervisory and Sube closed SW 7756 at Planters.

---

---

# *Xcel Energy South Control Center Daily Operations Report*

*Date: 8/15/2008*

---

---

**Out Time: In Time:**  
**(Begin:) (End:)**

10:27	10:55	Shell CO2 BKR 8960 CK out BKR and preform OP check  Released and terminated.
10:43	13:15	Shell C2 -115KV BKR 8955 - check recloser.
10:53	15:42	Deaf Smith Co Interchange test relays
11:07		SPP called for a TLR 3B on the imports.
11:39	20:47	Cunningham Sta unit #4 on line for voltage support. Cunningham Sta #4 unit off line.
12:53	13:38	Yoakum Co Interchange 115KV BKR 6H05 - test carrier and test relays
13:14	14:29	Denver City Interchange 115KV BKR's W930 & W915 - interrogate relays at Mustang also
13:31	17:20	Crosby Co Interchange to Tuco Interchange Y84 install jumpers East side of Hettler and close isolators west side of Idalou tap.
13:55	16:36	Taking TI down due to alarm, will be losing telemetering.
17:38	18:05	Carriers tested OK, except for the carriers at PCA. The RTU is still down.
22:00		TLR level 3a on SPP/SPS ties imports