
Xcel Energy South Control Center Daily Operations Report

Date: 12/14/2009

Out Time: In Time:
(Begin:) (End:)

6:43 Hastings to Northwest Interchange Z34
D/L clearance re-established for line maint.

6:43 Bush to Northwest Interchange V50
D/L clearance re-established for line maint.

7:26 SPP released TLR to level 0 on SPSNORTH_STH flow gate

9:06 Curry Co Interchange to Roosevelt Co Intg V78
Work completed TWR terminated

9:36 Roosevelt Co Interchange
Work completed TWR terminated

9:58 Roosevelt Co Interchange
TWR established for end to end checks of new relays

10:40 13:49 Dalhart Interchange
TWR established for condition assessment on bkr 5825
Work completed. TWR terminated.

12:30 Blackwater DC Tie out of service for maintenance.

13:27 Nichols Sta
Work complete. TWR terminated

14:35 Cunningham Sta to Whitten T39 - TWR for replacing switch
4J87and checking switch 4J53

17:30 17:54 Performed Carrier Tests

22:00 Kress Interchange - Scada shows low gas alarm on cap bkr
9708 cap bank. It is currently off line. Requested sube to
check.