
Xcel Energy South Control Center Daily Operations Report

Date: 1/2/2010

Out Time: In Time:
(Begin:) (End:)

13:00 Turned off carriers in alarm @ AMA S - Swisher (K63).
Turned back on.
" " " " " " Dallam - Etter (V64). Turned
back on.
" " " " " " Nichols - Grapevine (K53).
" " " " " " Canyon West - Osage (V5).
Turned back on.
" " " " " " Dalhart - Moore Co (T47).

17:39 18:20 SWPP issued a TLR 3B on Exports for SPSSPPTIES flow gate
SWPP released TLR 3B on SPSSPPTIES

19:03 19:40 Carriers tested
Pringle (1H30) - Harrington (FK75) did not test. Turned off on
both ends.

Self testing carriers: Dalhart (1J85) - Moore Co (M995) on ckt
T47 and
Nichols (BK16) - Hutchinson (1K06) on ckt K6 are still off.

21:27 22:01 Carriers tested OK, except for the ones that are turned off.

23:19 Amarillo South Interchange to Swisher Co Intg K63 carriers in
and out of alarm turned off on both ends.