
Xcel Energy South Control Center Daily Operations Report

Date: 1/23/2010

Out Time: In Time:
(Begin:) (End:)

1:43 3:38 Floyd Co Interchange to Tuco Interchange Z36 - Lighthouse REC believes the Brk. 8789 @ Wilson tap is opened. There is no RTU there. Notified DDC to dispatch a man.

Bkr. 8789 was closed @ 0338. Cause unknown.

7:37 15:51 SPP issued TLR on flow gate Temp 5 - Loss K46 (Plt X-Sundown) will overload K42 (Tolk- Tuco) for constraint management prior to taking Ckt V9 out for TWR to replace burned poles.
SPP released TLR to level 0.

8:03 15:38 Hale Co Interchange to Plant X Sta V09 - D/L TWR to replace burned poles

Released and Term.

9:29 SPP released TLR 3 on flow gate Temp 1 - the loss of K11, Bushland to Deaf Smith, will overload V5, Osage to Canyon

9:39 Cochran Co/Hockley Co Intg to Terry Co Intg Z25 - Received report circuit from E. Levelland to Terry pole broken leaning about 15 ft. off ground. Notified Trans Svcs supervisor.
Sending man to check.
Pole is between FB Sw 6706 and sw 6707. Can be isolated.

12:06 Cochran Co/Hockley Co Intg to Terry Co Intg Z25 - established D/L TWR to repair broken pole between FB sw 6706 and sw 6707. Stubbed pole from falling into road. Will repair Sunday.

16:09 20:17 Tolk Sta to Tuco Interchange K42 - D/L TWR to replace burnt poles.
Released and term.

21:15 SPP issued TLR 3B on flow gate Temp #1 - loss of K11 (Bushland to Deaf Smith) will overload V5 (Osage to Canyon West)

21:55 Perform carrier test.