
Xcel Energy South Control Center Daily Operations Report

Date: 2/26/2010

Out Time: In Time:
(Begin:) (End:)

3:05	3:05	Denver City Interchange to Seagraves Intg Y95 - 69kv Bkr W730 O/C. Cause unknown at this time. DCC reported catastrophic failure on OCR at Jaybee Sub.
7:51	14:29	Gray Co Interchange to Adobe Creek Z74 is under hot line conditions to dig foundations underneath the circuit.
8:58	8:58	Denver City Interchange to Seagraves Intg Y95 - 69kv Bkr W730 O/C. Crew in the process of Re-energizing Jaybee Sub.
11:59	17:00	Borden Interchange TWR established to replace oil in LTC
13:11	14:28	Wilson - TWR to Op Ck 8789 after failure to Close/Reclose for a fault.
	15:34	Roosevelt Co Interchange - Breaker 8917 has returned to service for the weekend.
17:30		Carriers tested good.