
Xcel Energy South Control Center Daily Operations Report

Date: 2/12/2010

Out Time: *In Time:*
(Begin:) *(End:)*

	8:27	Harrington Sta replace SW'S FK52 and FK51.
8:47	9:06	Denver City Interchange 115 KV capacitor breaker W955 out for operational checks.
9:08	9:55	Pantex South BKR 5J25 CA and Mechanism. Work completed and TWR terminated.
9:26	17:31	Cunningham Sta #1 Start up transformer out for plant controls retrofit.
9:37	9:57	Denver City Interchange 115 KV capacitor breaker W975 out for operational checks.
10:00	13:20	Denver City Interchange bus tie breaker W940 out for operational checks
10:20	11:25	Pantex North TWR established to CA bkr 5J10
13:03	14:14	Yoakum Co Interchange 115 KV breaker 6H95 out to add SF-6 gas.
	13:36	Yoakum Co Interchange 230 KV breaker 6K50 back in service.
15:58	16:27	Blackhawk Interchange BKR 1H85 TWR to add SF6 gas.
	16:17	East Plant Interchange to Osage Sw Sta V43 line maintenance
	16:17	East Plant Intg to Osage Sw Sta.
16:19	16:31	Carriers tested O.K.